PHONE 509-933-7050

ELLENSBURG CEMENT PRODUCTS, INC.

CRUSHED GRAVEL WASHED SAND & GRAVEL

READY MIXED CONCRETE

CONT. REG, # ELLEN CP 225 DP

PRICE ALLOWS 8 MINUTES PER YARD TO UNLOAD TRUCK AFTER ARRIVAL. ALL TIME OVER THIS CHARGED FOR AT CURRENT RATES.

CUSTOMER IS RESPONSIBLE FOR PROVIDING ACCEPTABLE WASHDOWN AREA.

SHIP TO:

SOLD TO:

GRAHAM CONTRACTING LTD 568 lst AVE S SEATTLE WA 98104

98844

I-90 MILE MARKER 102 MILE MARKER 102 WB COME IN EAST END OF BRIDGE NICK MALATESTA 425.301.8054 VERIFY DESIGNATED WASHOUT

TIME LOAD SIZE MIX CY/M3 ORDERED ZONE DRIVER/TRUCK # COUNTER START TICKET # 06:06 313 3.00 23.00 157 0.00 170429 P.O. # DATE LOAD # CY/M3 DEL BATCH # WATER TRIM SLUMP PLANT 09/25/2019 3200023428 3.00 4.00 NRMCA PLE

WARNING IRRITATING TO THE SKIN AND EYES

Contains Portland Cement. Wear Rubber Boots and Gloves. PROLONGED CONTACT MAY CAUSE BURNS. Avoid Contact With Eyes and Prolonged Contact With Skin. In Case of Contact With Skin or Eyes, Flush Thoroughly With Water. If Irritation Persists, Get Medical Attention. KEEP AWAY FROM CHILDREN I HAVE READ AND
UNDERSTAND ALL
WARNINGS, PROPERTY
DAMAGE RELEASE
INFORMATION AND
WARRANTY INFORMATION
ON THE REVERSE SIDE OF
THIS TICKET.

Excessive Water is Detrimental to Concrete Performance H₂O Added By Request/Authorized By

_GAL X

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE, DAMAGE RELEASE AND WARRANTY INFORMATION ON THE REVERSE SIDE OF FORM.

LOAD RECEIVED BY

QUANTITY CODE DESCRIPTION UNIT PRICE EXTENDED PRICE 3.00 313 40000 HPC EBURG 3.00 4 ENVIRONDAL 13.00 2 HOUR DELAT BET DEL2 0 1.00 SHORT LOAD SHORT LOAD UNDER S C Shown RETURNED TO PLANT LEFT JOB FINISH UNLOADING TIME ALLOWED DELAY EXPLANATION/CYLINDER TEST TAKEN 1, JOB NOT READY ACCIDENT SLOW POUR OR PUMP TRUCK AHEAD ON JOB LEFT PLANT CONTRACTOR BROKE DOWN ARRIVED JOB START UNLOADING 9. OTHER C: 44 Subtotal: TOTAL ROUND TRIP TOTAL AT JOB UNLOADING TIME Taxe : CEMO1 -MOTES-TV-2018 GRAND TOTAL

BATCH DATA				b. 1							
Date/Time 09/25/2019	Q\$:56		rket 170429	Tenc 157		MixCode 913			me/Id 98	944	
Material 1 1/2 3/4 3ANB CEM03 CEM02 MAT01 MURA MBAE90 DELVO	-38D 727 1200 1205 480 100 27.00 26.00 2.90 8.00	Target 2,220 3,610 3,759 1,440 300 52.32 108.00 11.70 139.20	Actual 2,200 3,600 2,720 1,460 290 55.00 108.00 11.00 136.00	lb lb	Vare -0.9 -0.3 -1.1 -1.4 -3.3 5.1 0.0 -6.0 -2.3	WatC 4.85 1.30 18.03	Moist 1.82m 0.30m 4.00m	1	Load Returned Mix Slump Mix Wat(GL) Trim Wat(GL) Truck Wat(GL) Act Wat(GL) Add Wat(GL) Mix Wt/Cm Act Wt/Cm	80.93 0.53 0.3882	
						WEIGHMAS	STER SIGNATURE	Χ			

PHONE 509-933-7050

ELLENSBURG CEMENT PRODUCTS, INC.

READY MIXED CONCRETE

CONT. REG. # ELLEN CP 225 DP

PRICE ALLOWS 8 MINUTES PER YARD TO UNLOAD TRUCK AFTER ARRIVAL, ALL TIME OVER THIS CHARGED FOR AT CURRENT RATES.

CUSTOMER IS RESPONSIBLE FOR PROVIDING ACCEPTABLE WASHDOWN AREA.

SHIP TO:

SAND & GRAVEL SOLD TO:

SRAHAM CONTRACTING LTD 585 lst AVE 8 SEATCLE WA 98104

CRUSHED GRAVEL

WASHED

98844

I-90 MILE MARKER 102
MILE MARKER 102 WB
COME IN EAST END OF BRIDGE
NICK MALATESTA 425,301,3084
VERIFY DESIGNATED WASHOUT

TIME	MIX	LOAD SIZE	CY/M3 ORDERED	ZONE	DRIVER/TRUCK #	COUNTER START	TICKET #
07:15	313	5 00	22.00	t-vijetti	ası	0.00	170496
DATE	P.O. #	LOAD #	CY/M3 DEL.	BATCH #	water trim	SLUMP	PLANT
09/25/2019	3200023422		9.00			4.00	NRMCA PUT
			Maria Da Hallanda		F	- Detrimental to Com	

WARNING IRRITATING TO THE SKIN AND EYES

Contains Portland Cement. Wear Rubber Boots and Gloves. PROLONGED CONTACT MAY CAUSE BURNS. Avoid Contact With Eyes and Prolonged Contact With Skin. In Case of Contact With Skin or Eyes, Flush Thoroughly With Water. If Irritation Persists, Get Medical Attention. KEEP AWAY FROM CHILDREN I HAVE READ AND
UNDERSTAND ALL
WARNINGS, PROPERTY
DAMAGE RELEASE
INFORMATION AND
WARRANTY INFORMATION
ON THE REVERSE SIDE OF
THIS TICKET.

Excessive Water is Detrimental to Concrete Performance H₂O Added By Request/Authorized By

GAL >

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE, DAMAGE RELEASE AND WARRANTY INFORMATION ON THE REVERSE SIDE OF FORM.

QUANTITY	CODE	DESCRIPTION	Sugar Lyxida o K		UNIT PRICE	EXTENDED PRICE
5.00	313	40000 H9C	EBURG	69214	Hamelika jarisi	111
5 00	9 1	I ENVIRONENT	AL EED.		Commercial designation of the	9/6
8.90	DESS.0	3 HOUR DEPT	AY SEW	1- 4751 22		
				BI #24.01	TALKS.	5
No. of Street,				9/25/19	Name of	1
26						No. of the last of
RETURNED TO PLANT	LEFT JOB	FINISH UNLOADING	TIME ALLOWED	DELAY EXPLANATION/CYLINDER TEST TAKEN		
RETURNED TO FLANT	LEIT JOB	TIMISH UNLUADING	THUE ALLOWED	BEEN EN CHIMATION OF ENDER FEOT TAKEN		

RETURNED TO PLANT	LEFT JOB	FINISH UNLOADING	TIME ALLOWED	DELAY EXPLANATION/CY	LINDER TEST TAKEN	partition and the state of the
			Alternation of	1. JOB NOT READY 2. SLOW POUR OR PUMP 3. TRUCK AHEAD ON JOB	6. TRUCK BROKE DOWN 7. ACCIDENT 8. CITATION	
LEFT PLANT	ARRIVED JOB	START UNLOADING		4. CONTRACTOR BROKE DOWN 5. ADDED WATER	9 OTHER	ASPER PROPERTY.
730	7 35					Subtotal:
TOTAL ROUND TRIP	TOTAL AT JOB	UNLOADING TIME	CEMOL- MORE	Th-2018-11	selventri tea tou	Tax:
7-5			CEMOS: 12- CEMOS: XXX	CLASS F	e ijawa Havea	GRAND TOTAL

BATCH DATA						1			Last / Tax		
Date/Time		Tak	rket	1 1110	k M	igCode	Custos	ima Ha	uner/Id 91	多种性	1.7
09/25/2019	07:15		170435	151	3	LD	GP&HAL	I COM	MACTING LTD		
						*	1				
Material	360	Treges	Acres is as a L	Unan	Var 8	WasC	Moist		Load	5.00	
1 1/2	727	3,702	2,920	Ib -	0 - 8	18.08	1.02m	1	Returned	0.00	
3/4	1.200	6,018	6.0204	Lb	0.0	2.15	0.30m	1 1	Mix Slump	4.00	
SAND	1208	6,255	5,250	3.20	-0.1	30.05	4.00m	1.1	Mix Wat (GL)	92.00	
CEM03	49.6	2,400	2, 310	2.35	0.4			. 4	Trim Wat (GL	0.00	
CEM05	100	500	485	1.25	-3.0	1		1	Truck Wat (G	L) 0.00	
>WATO1	27.50	89.71	92.00	731	2.6	*		1	Ret Wat (GL)	135.64	
MWRA	25.00	150.00	180.00	C3 15	0.0	1		- 1	Add Wat (GL)	1.53	
MBAE90	0.80	19 00	10.00	0%	-5.3	1		- 1	Mix Wt/Cm	0.3954	
DELVO	0.00	282.00	220.00	C) All	-1.7			- 1	Act Wt/Cm	0.3907	
May a					- N - 3	1					
I Tree in	- 4		7		- V	WEIGHMAS	STER SIGNATURE	Χ			

PHONE 509-933-7050

ELLENSBURG CEMENT PRODUCTS, INC.

CRUSHED GRAVEL WASHED SAND & GRAVEL

READY MIXED CONCRETE

CONT. REG. # ELLEN CP 225 DP

PRICE ALLOWS 8 MINUTES PER YARD TO UNLOAD TRUCK AFTER ARRIVAL. ALL TIME OVER THIS CHARGED FOR AT CURRENT RATES.

CUSTOMER IS RESPONSIBLE FOR PROVIDING ACCEPTABLE WASHDOWN AREA.

SHIP TO:

SOLD TO:

GRANAM CONTRACTING LTD 568 lst AVE 8 SEATTLE WA 98104

99944

I-90 MILE MARKER 102 MILE MARKER 102 WE COME IN EAST END OF BRIDGE NICK MALATESTA 425,301.8054 VERIPY DESIGNATED WASHOUT

TIME	MIX	LOAD SIZE	CY/M3 ORDERED	ZONE	ØRIVER/TRUCK #	COUNTER START	TICKET#
08:08	313	5.00	29.00		1.59	0100	170 443
PATE	P.O. #	LOAD #	CY/M3 DEL.	BATCH #	WATER TRIM	SLUMP	PLANT
09/25/2019	920002342	PORNITA INTE	12.00	2		4.00	NRMCA PLT

WARNING IRRITATING TO THE SKIN AND EYES

Contains Portland Cement. Wear Rubber Boots and Gloves. PROLONGED CONTACT MAY CAUSE BURNS. Avoid Contact With Eyes and Prolonged Contact With Skin. In Case of Contact With Skin or Eyes, Flush Thoroughly With Water. If Irritation Persists, Get Medical Attention. KEEP AWAY FROM CHILDREN I HAVE READ AND
UNDERSTAND ALL
WARNINGS, PROPERTY
DAMAGE RELEASE
INFORMATION AND
WARRANTY INFORMATION
ON THE REVERSE SIDE OF
THIS TICKET

Excessive Water is Detrimental to Concrete Performance H₂O Added By Request/Authorized By

GAL X

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE, DAMAGE RELEASE AND WARRANTY INFORMATION ON THE REVERSE SIDE OF FORM.

LOAD RECEIVED BY

 QUANTITY
 CODE
 DESCRIPTION

 5.00
 313
 40000 MPC
 EBURG

 5.00
 4
 ENVIRONMENTAL FEE

 5.00
 DEL2.0
 2 HOUR DELAY SET

UNIT PRICE EXTENDED PRICE

C9214 9/25/19 3/6

BI #24.01

RETURNED TO PLANT	ETURNED TO PLANT LEFT JOB		TIME ALLOWED	DELAY EXPLANATION/CY	LINDER TEST TAKEN
				1. JOB NOT READY 2. SLOW POUR OR PUMP 3. TRUCK AHEAD ON JOB	6. TRUCK BROKE DOWN 7. ACCIDENT 8. CITATION
LEFT PLANT	ARRIVED JOB	START UNLOADING		4. CONTRACTOR BROKE DOWN 5. ADDED WATER	9. OTHER
818	877	8:30		3. RODED WATER	
0110	012	0.20	estite valed the	CL THE DAMES IN NOT	THE LOW HAVE
TOTAL ROUND TRIP	TOTAL AT JOB	UNLOADING TIME	CTMO 1 - MODE	TL-2018-11	UITE OF THE REAL
		9111	CEMOS I' YOU'		wileini karni
		1, 3	CHARLES OF THE PARTY OF	3	

Juneotal. Tan:

GRAND TOTAL

BATCH DATA		
Date/Time 09/25/2019 08:09	Ticket Truck Milcode Customer Hame, Id 98844 170943 159 91 GRAHAM CONTRACTING LTD	
Material 38D 1 1/2 72 3/4 120 3AND 120 CEM02 48 CEM02 10 WATO1 27.5 MWRA 36.0 MBAE90 3.8 DELVO 8.0	6,018 5,980 1b -1.0 1-16 0.30m Mix Slump 4.5 5,266 5,220 1b -0.7 f0.05 4.00m Mix Wat (GL) 92.0 2,400 2,295 1b -0.2 Trim Wat (GL) 0.0 Truck Wat (GL) 0.0 Fact Wat (GL) 0.0 S9.71 82.00 gal 2.5 Act Wat (GL) 125.3 Act Wat (GL) 1.25.3 180.00 180.00 om 0.0 Add Wat (GL) 1.5 Mix Wat (GL) 1.5 Mix Wat (GL) 1.5 Mix Wat (GL) 1.5 Act Wat (70 70 70 70 70 70 70 75

PHONE 509-933-7050

ELLENSBURG CEMENT PRODUCTS, INC.

READY MIXED CONCRETE

CONT. REG. # ELLEN CP 225 DP

PRICE ALLOWS 8 MINUTES PER YARD TO UNLOAD TRUCK AFTER ARRIVAL, ALL TIME OVER THIS CHARGED FOR AT CURRENT RATES.

CUSTOMER IS RESPONSIBLE FOR PROVIDING ACCEPTABLE WASHDOWN AREA.

SHIP TO:

NRMCA PL

SOLD TO:

GRAHAM CONTRACTING LTD 568 lst AVE 3 SEATENE WA 98104

CRUSHED GRAVEL

WASHED

SAND & GRAVEL

LOAD SIZE

5.00

LOAD #

98844

TIME

DATE

09/25/2019

08:52

I-90 MILE MARKER 102 MILE MARKER 102 WB COME IN EAST END OF BRIDGE NICK MALATESTA 425.301.8054

NICK MALATESTA 425.301.8054
VERIEY DESIGNATED WASHOUT

ZONE DRIVER/TRUCK # COUNTER START TICKET #

150 0.00 170.449

BATCH # WATER TRIM SLUMP PLANT

WARNING IRRITATING TO THE SKIN AND EYES

32000234289

MIX

PO #

212

Contains Portland Cement. Wear Rubber Boots and Gloves. PROLONGED CONTACT MAY CAUSE BURNS. Avoid Contact With Eyes and Prolonged Contact With Skin. In Case of Contact With Skin or Eyes, Flush Thoroughly With Water. If Irritation Persists, Get Medical Attention. KEEP AWAY FROM CHILDREN I HAVE READ AND
UNDERSTAND ALL
WARNINGS, PROPERTY
DAMAGE RELEASE
INFORMATION AND
WARRANTY INFORMATION
ON THE REVERSE SIDE OF
THIS TICKET.

CY/M3 ORDERED

CY/M3 DEL.

23.00

18.00

Excessive Water is Detrimental to Concrete Performance H₂O Added By Request/Authorized By

4.00

GAL X

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE, DAMAGE RELEASE AND WARRANTY INFORMATION ON THE REVERSE SIDE OF FORM.

LOAD RECEIVED BY:

QUANTITY CODE DESCRIPTION UNIT PRICE EXTENDED PRICE 8.00 313 4000D RPC Shown Blus EBURG ACT #01334425 5.00 4 ENVIROMENTAL FEE 5.00 DEL2.0 2 HOUR DELAY SET 12GEDE 126692 (28 DAY (PAG 1) (2 DAY 17 A 17B 84 18B 19A MA RETURNED TO PLANT LEFT JOB FINISH UNLOADING TIME ALLOWED DELAY EXPLANATION/CYLINDER TEST TAKEN 1. JOB NOT READY 6. TRUCK BROKE DOWN SLOW POUR OR PUMP TRUCK AHEAD ON JOB 7. ACCIDENT 8. CITATION LEFT PLANT ARRIVED JOB START UNLOADING CONTRACTOR BROKE DOWN 9. OTHER ADDED WATER 9:33 Subtotal: TOTAL ROUND TRIP TOTAL AT JOB UNLOADING TIME CEMO1: WTR-IL-2018-1 CEM02: 12-18 CLASS F GRAND TOTAL XXXXXXXXXXXXXX

BATCH DATA									
Date/Time 09/25/2019	00:52		cket 170449	Truc 150	rk.	MixCode 313		mer Name/Id 98844 M CONTRACTING LTD	
Material >1 1/2 3/4 >SAND CEM03 CEM02 >WAT01 MWRA MBAE90 DELVO	727 1200 1205 400 100 27.50 36.00 9.80 8.00	Target 3,701 6,018 6,266 2,400 500 69.71 180.00 19.00 232.00	Actual 3,760 6,000 6,220 2,395 485 92.00 180.00 18.00 228.00	Unit lb lb lb lb gal cs os	Var% 1.6 -0.3 -0.7 -0.2 -3.0 2.6 0.0 -5.3 -1.7	8.08 2.16 30.05	Moist 1.82m 0.30m 4.80m	Load	
					e i bir Jijane ii	WEIGHMA	STER SIGNATURE	X	

PHONE 509-933-7050

ELLENSBURG CEMENT PRODUCTS, INC.

READY MIXED CONCRETE

PRICE ALLOWS 8 MINUTES PER YARD TO UNLOAD TRUCK AFTER ARRIVAL. ALL TIME OVER THIS CHARGED FOR AT CURRENT RATES.

CUSTOMER IS RESPONSIBLE FOR PROVIDING ACCEPTABLE WASHDOWN AREA.

SHIP TO:

SAND & GRAVEL SOLD TO:

GRAHAM CONTRACTING LTD 568 1st AVE 8 SEATTLE WA 98104

CRUSHED GRAVEL

WASHED

98844

CONT. REG. # ELLEN CP 225 DP

I-90 MILE MARKER 102
MILE MARKER 102 WB
COME IN EAST END OF BRIDGE
NICK MALATESTA 425.301.8054
WERIEY DESIGNATED WASHOUT

TIME	MIX	LOAD SIZE	CY/M3 ORDERED	ZONE	DRIVER/TRUCK #	COUNTER START	TICKET#
09:33	313	5.00	23.00		169	0.00	170452
DATE	P.O. #	LOAD #	CY/M3 DEL.	BATCH #	WATER TRIM	SLUMP	PLANT
09/25/2019	3200023425		29.00			4.00	NEMCA PL

WARNING IRRITATING TO THE SKIN AND EYES

Contains Portland Cement. Wear Rubber Boots and Gloves. PROLONGED CONTACT MAY CAUSE BURNS. Avoid Contact With Eyes and Prolonged Contact With Skin. In Case of Contact With Skin or Eyes, Flush Thoroughly With Water. If Irritation Persists, Get Medical Attention. KEEP AWAY FROM CHILDREN I HAVE READ AND
UNDERSTAND ALL
WARNINGS, PROPERTY
DAMAGE RELEASE
INFORMATION AND
WARRANTY INFORMATION
ON THE REVERSE SIDE OF
THIS TICKET.

Excessive Water is Detrimental to Concrete Performance H₂O Added By Request/Authorized By

GAL X

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE, DAMAGE RELEASE AND WARRANTY INFORMATION ON THE REVERSE SIDE OF FORM.

UNIT PRICE

LOAD RECEIVED BY:

QUANTITY CODE DESCRIPTION

5.00 313 4000D HPC EBURG

5.00 4 ENVIRONMENTAL FEE

5.00 DEL2.0 2 HOUR DELAY SET

C924 BI #24.01 9/25/19 EXTENDED PRICE

RETURNED TO PLANT	LEFT JOB	FINISH UNLOADING	TIME ALLOWED	DELAY EXPLANATION/CYL	INDER TEST TAKEN
	- 1		- PLEATER TO SERVICE A SER	1. JOB NOT READY 2. SLOW POUR OR PUMP 3. TRUCK AHEAD ON JOB	6 TRUCK BROKE DOWN 7 ACCIDENT 8 CITATION
LEFT PLANT	ARRIVED JOB	START UNLOADING		4 CONTRACTOR BROKE DOWN 5 ADDED WATER	9. OTHER
0946	953			WALLEN WALLEN	dentity of
TOTAL ROUND TRIP	TOTAL AT JOB	UNLOADING TIME	CEMOI - MTR-	TL-2018-11	ng in the 18
			CEM02: 12-1	8 CLASS F	

Subtotal:

GRAND TOTAL

There-

BATCH DATA						-		
Date/Time 09/25/2019	09:33	Ts.	oket 170452	True 169	zh	MixCode 313		er Name/Id 98844 CONTRACTING LTD
Material 1 1/2 2/4 SAND CEM03 CEM02 WAT01 MWRA MBAE90 DELVO	\$3D 727 1200 1205 480 100 27.50 26.00 3.80 8.00	Target 3,701 6,018 5,265 2,400 500 89.71 180.00 19.00 232.00	Actual 3,700 5,980 5,220 2,415 515 92.00 180.00 18.00 228.00	lb lb lb lb gal oz	Vara 0.0 -0.5 -0.7 0.6 3.0 2.6 0.0 -5.3 -1.7	8.08 2.16 30.05	Moist 1.82m 0.30m 4.00m	Load

WEIGHMASTER SIGNATURE X

PHONE 509-933-7050

ELLENSBURG CEMENT PRODUCTS, INC.

CRUSHED GRAVEL:

SAND & GRAVEL

READY MIXED CONCRETE

CONT. REG. # ELLEN CP 225 DP

PRICE ALLOWS 8 MINUTES PER YARD TO UNLOAD TRUCK AFTER ARRIVAL. ALL TIME OVER THIS CHARGED FOR AT CURRENT RATES.

CUSTOMER IS RESPONSIBLE FOR PROVIDING ACCEPTABLE WASHDOWN AREA.

SHIP TO:

SOLD TO:

STATEM CONTRACTING LTD 568 lsc AVE S SEATTLE WA 98104

98544

I-90 MILE MARKER 102 MILE MARKER 102 WB COME IN EAST END OF BRIDGE NICK MALATESTA 425.201.8054 VERIFY DESIGNATED WASHOUT

ACCOUNT OF THE PARTY OF THE PAR	Committee of the commit				
1.00	24.00		162	0.00	170459
# LOAD #	CY/M3 DEL.	BATCH#	WATER TRIM	SLUMP	PLANT
102342 6	24.00			4.00	NRMCA PLT
0	0.# LOAD#). # LOAD # CY/M3 DEL.	0.# LOAD # CY/M3 DEL. BATCH # 00234265 24.00	0.# LOAD# CY/M3 DEL. BATCH# WATER TRIM 00234285 24.00	0.# LOAD# CY/M3 DEL. BATCH# WATER TRIM SLUMP 00234285 24.00 4.00

WARNING IRRITATING TO THE SKIN AND EYES

Contains Portland Cement. Wear Rubber-Boots and Gloves. PROLONGED CONTACT MAY CAUSE BURNS. Avoid Contact With Eyes and Prolonged Contact With Skin. In Case of Contact With Skin or Eyes, Flush Thoroughly With Water. If Irritation Persists, Get Medical Attention. KEEP AWAY FROM CHILDREN I HAVE READ AND
UNDERSTAND ALL
WARNINGS, PROPERTY
DAMAGE RELEASE
INFORMATION AND
WARRANTY INFORMATION
ON THE REVERSE SIDE OF
THIS TICKET.

Excessive Water is Detrimental to Concrete Performance H_2O Added By Request/Authorized By

GAL >

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE, DAMAGE RELEASE AND WARRANTY INFORMATION ON THE REVERSE SIDE OF FORM.

LOAD RECEIVED BY:

X

UNIT PRICE EXTENDED PRICE

QUANTITY	CODE	DESCRIPTION
1.00	212	40000 HPC ESUNG
1 00	4]	ENVIRONENTAL FEE
1.00	0.5430	2 HOUR DELAY SET

C9214 BI #24.01

06/6

RETURNED TO PLANT	LEFT JOB	FINISH UNLOADING	TIME ALLOWED	DELAY EXPLANATION/CYLINDER TEST TAKEN
(1)c	(C.16		11/1/20	1. JOB NOT READY 6, TRUCK BROKE DOWN 2. SLOW POUR OR PUMP 7. ACCIDENT 8. CITATION 8. CITATION
LEFT PLANT	ARRIVED JOB	START UNLOADING		4. CONTRACTOR BROKE DOWN 9. OTHER 5. ADDED WATER
1:00				
TOTAL ROUND TRIP	TOTAL AT JOB	UNLOADING TIME	CEMOI MTD-	TL-2018-17
			CEM02: 12-1	8 CLASS F
			CEMBS: XXXX	XXXXXXXXX

Subtotal:
Tak:
Total:
GRAND TOTAL

BATCH DATA	4-								
Date/Time		The state of the s	cket	True	sh M	ixCode	Custosa	er Name/Id 98844	
09/25/2019	10:52		1.70459	162	. Pro-	13		CONTRACTING LTD	
Material	33D	Target	Actual	Unit	Vare	WatsC	Moist	Load 1.00	_
1 1/2	727	740	760	1b.	2.7	1.62	1.82m	Returned 0.00 .5	
3/4	1200	1,203	1,180	1.6	-2.0	0.43	0.30m	Mix Slump 4.00	_
SAND	1205	1,253	1,220	15	-2.6	6.01	4.00m	Mix Wat (GL) 0.00	
CEM03	480	480	510	1.b	6.3			Trim Wat (Gh) 0.00	
CEM02	100	100	90	1b	-10.0			Truck Wat (GL) 15.00	
WATO1	27.50	2.94	0.00	gal	-100.0	18 4. "		Act Wat(GL) 23.58	
WRA	36.00	36.00	36.00	0.5	0.0	(4)		Add Wat(GL) 4.87	
MBAE90	3780	3.80	3.00	08	-21.1			Mix Wt/Cm 0.2954	
DELVO	0.00	45.40	44.00	0.8	-5.2	STORES.		Act Wt/Cm 0.3278	

WEIGHMASTER SIGNATURE X

PHONE 509-933-7050

ELLENSBURG CEMENT PRODUCTS, INC.

CRUSHED GRAVEL WASHED SAND & GRAVEL

READY MIXED CONCRETE

CONT. REG. # ELLEN CP 225 DP

PRICE ALLOWS 8 MINUTES PER YARD TO UNLOAD TRUCK AFTER ARRIVAL. ALL TIME OVER THIS CHARGED FOR AT CURRENT RATES.

CUSTOMER IS RESPONSIBLE FOR PROVIDING ACCEPTABLE WASHDOWN AREA.

SHIP TO:

SOLD TO:

GRAHAM CONTRACTING LTD

SEATTLE WA 98104

566 lst AVE S

YANDA RIVER BRIDGES I SO

COME IN ON THE BAST END

9등반조대

WEREPY DESIGNATED WASHOUT

TIME	MIX	LOAD SIZE	CY/M3 ORDERED	ZONE	DRIVER/TRUCK #	COUNTER START	TICKET #
15:10	326	3.00	3.00		159	0.00	170546
DATE	P.O. #	LOAD #	CY/M3 DEL.	BATCH #	WATER TRIM	SLUMP	PLANT
09/30/2019	3200023425		3.00			8.00	MRMCA PL

WARNING IRRITATING TO THE SKIN AND EYES

Contains Portland Cement. Wear Rubber Boots and Gloves. PROLONGED CONTACT MAY CAUSE BURNS. Avoid Contact With Eyes and Prolonged Contact With Skin. In Case of Contact With Skin or Eyes, Flush Thoroughly With Water. If Irritation Persists, Get Medical Attention. KEEP AWAY FROM CHILDREN I HAVE READ AND
UNDERSTAND ALL
WARNINGS, PROPERTY
DAMAGE RELEASE
INFORMATION AND
WARRANTY INFORMATION
ON THE REVERSE SIDE OF
THIS TICKET.

Excessive Water is Detrimental to Concrete Performance H₂O Added By Request/Authorized By

GAL X

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE, DAMAGE RELEASE AND WARRANTY INFORMATION ON THE REVERSE SIDE OF FORM.

UNIT PRICE

QUANTITY CODE DESCRIPTION

3.00 328 CLASS M

3.00 4 ENVIRONMENTAL FEE

1.00 SHORT LOAD SHORT LOAD UNDER 5 CY

1.00 80147330 FD 34A 3 FD 34B

1 Day 80127031 FD 25 A \$ FD 25 B

BI \$30.01

LOAD RECEIVED BY:

C9214 SLUMP = 5.0" AiR = 7.090 TEMP = 640 Shawn Glass

EXTENDED PRICE

RETURNED TO PLANT	LEFT JOB	FINISH UNLOADING	TIME ALLOWED	DELAY EXPLANATION/CYLINDER TEST TAKE
			I divinia	1, JOB NOT READY 6, TRUCK BROKE DOW 2, SLOW POUR OR PUMP 7, ACCIDENT 3, TRUCK AHEAD ON JOB 8, CITATION
LEFT PLANT	ARRIVED JOB	START UNLOADING		4. CONTRACTOR BROKE DOWN 9. OTHER 5. ADDED WATER
3/5	in al nichtes	rabit entillentil ex ume falulinae		The self-or the self-or self-o
TOTAL ROUND TRIP	TOTAL AT JOB	UNLOADING TIME	CEM02: 12-	-IL-2010-11 18 CLASS F

Subtotal:

ACL # 01334465

GRAND TOTAL

								The second secon
Date/Time		Ti	cket	Truc	k	MixCode		mer Name/Id 90094
03/30/5013	15:10		170546	153		328	GRAHA	AM CONTRACTING LTD
Material	330	Target	Actual	Unit	Vari	WatC	Moist	Load 3.00
PG	1650	4,905	4.080	1b	-0.5	4.24	0 - 7 Lm	(Returned 0.00 d.0)
SAND	1230	2,993	4,180	1.b	41 PX	19.15	4.00m	Mix Slump 5.00
CEMOI	705	2,115	2.105	1b	-0.5			Mix Wat(GL) 53.00
MATOI	20 90	50 50	68_00	gal	4.0			Trim Wat (GL) -2.00
PEGA.	35.00	108.00	100.00	OS	0.0			Pruck Wat(GL) 0.00
MURA	84.00	192.00	192.00	OS	0.0			Act Wat(GL) 89.67
MBAE90	2,20	8_90	7.00	OS	1 4			Add Wat (GL) -0.10
A. S.								Mix Wb/Cm 0.2549
								Act Wt/Cm 0.3553
			7					
						WEIGHMA	ASTER SIGNATURE	X

PHONE 509-933-7050

ELLENSBURG EMENT PRODUCTS, INC.

READY MIXED CONCRETE

PRICE ALLOWS 8 MINUTES PER YARD TO UNLOAD TRUCK AFTER ARRIVAL. ALL TIME OVER THIS CHARGED FOR AT CURRENT RATES.

CUSTOMER IS RESPONSIBLE FOR PROVIDING ACCEPTABLE WASHDOWN AREA.

SHIP TO:

CRUSHED GRAVEL WASHED SAND & GRAVEL

GRAHAM CONTRACTING LTD

568 lst AVE 3

SEATTLE WA 98104

CONT. REG. # ELLEN CP 225 DP

YAKIMA RIVER BRIDGES I 90 MP 102

COME IN ON THE WEST END

98844

SOLD TO:

WERIFY DESIGNATED WASHOUT

TIME	MIX	LOAD SIZE	CY/M3 ORDERED	ZONE	DRIVER/TRUCK #	COUNTER START	TICKET#
14:19	328	3.00	3.00	ry hillery.	153	0.00	170576
DATE	P.O. #	LOAD #	CY/M3 DEL	BATCH #	WATER TRIM	SLUMP	PLANT
10/01/2019	3200023428		3.00			5.00	NRMCA PL

WARNING **IRRITATING TO THE SKIN AND EYES**

Contains Portland Cement, Wear Rubber Boots and Gloves. PROLONGED CONTACT MAY CAUSE BURNS. Avoid Contact With Eyes and Prolonged Contact With Skin. In Case of Contact With Skin or Eyes, Flush Thoroughly With Water, If Irritation Persists, Get Medical Attention. KEEP AWAY FROM CHILDREN

I HAVE READ AND **UNDERSTAND ALL** WARNINGS, PROPERTY DAMAGE RELEASE INFORMATION AND WARRANTY INFORMATION ON THE REVERSE SIDE OF THIS TICKET.

X

Excessive Water is Detrimental to Concrete Performance H₂O Added By Request/Authorized By

GAL X

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE, DAMAGE RELEASE AND WARRANTY INFORMATION ON THE REVERSE SIDE OF FORM.

QUANTITY	CODE	DESCRIPTION	which is a control to the		UNIT PRICE EXTENDED PRIC
3.00 3.00 1.00	328 4 SHORT LO	CLASS M ENVIROMENT AD SHORT LOAD	AL FEE UNDER 5 CY	154N Bridge Sey #5/Po	35.01 BI # 30.01
	ay , 12.	7059 7054 - 1270	FU 2	64 \$ FU 1613	Amb 51' Conc 70' Slump 33/4
RETURNED TO PLANT	LEFT JOB	FINISH UNLOADING	TIME ALLOWED	DELAY EXPLANATION/CYLINDER TEST TAKEN	Air 6.6
7-3-6	761 .**	-2-	TVASIB	1. JOB NOT READY 6. TRUCK BROKE DOWN 2. SLOW POUR OR PUMP 7. ACCIDENT 3. TRUCK AHEAD ON JOB 8. CITATION	Shenin Glass ACI \$0/334425
LEFT PLANT	ARRIVED JOB	START UNLOADING		CONTRACTOR BROKE DOWN OTHER ADDED WATER	ACT #0/334425
225	- I fine him h	14:54	arijum mritar Erti Arijum mritar Erti	o personnedkojn dendas sigli kolescojn personalism	Subtotal:
TOTAL ROUND TRIP	TOTAL AT JOB	UNLOADING TIME	CEMO1 - MTR	-TL-2018-11	Tax:
		Leasternal (As a seal	CEM02 - 12-		GRAND TOTAL

BAICH DAIA								
Date/Time 10/01/2019	14:19		c ket 170576	Truc 153		lixCode 28		er Name/Id 98844 CONTRACTING LTD
Material PG SAND CEM01 WAT01 WRA MWRA MWRA MBAE90	33D 1650 1280 705 30.00 35.00 64.00 2.30	Target 4,985 3,992 2,115 56.60 108.00 192.00 6.90	Actual 4,940 4,240 2,100 59.00 108.00 192.00 6.00	Unit lb lb lb gal os os	Vac4 -0.9 6.2 -0.7 4.2 0.0 0.0 -13.0	WatC 4.24 19.15	Moist 0.71m 4.00m	Load 3.00 Returned 0.00 1.5 Mix Slump 5.00 Mix Wat(GL) 59.00 Trim Wat(GL) 0.00 Truck Wat(GL)10.00 Act Wat(GL) 95.93 Add Wat(GL) -6.57 Mix Wt/Cm 0.3549 Act Wt/Cm 0.3810
						WEIGHMA	STER SIGNATURE	X

PHONE 509-933-7050

ELLENSBURG CEMENT PRODUCTS, INC.

READY MIXED CONCRETE

PRICE ALLOWS 8 MINUTES PER YARD TO UNLOAD TRUCK AFTER ARRIVAL. ALL TIME OVER THIS CHARGED FOR AT CURRENT RATES.

CUSTOMER IS RESPONSIBLE FOR PROVIDING ACCEPTABLE WASHDOWN AREA.

CRUSHED GRAVEL WASHED SAND & GRAVEL

CONT. REG. # ELLEN CP 225 DP

SHIP TO:

SOLD TO:

GRAHAM CONTRACTING LTD 568 let AVE S SEATTLE WA 98104

YAKIMA RIVER BRIDGES I 90 MP 102

COME IN ON west END OF BRIDGE

20000

VERIFY DESIGNATED WASHOUT

TIME	MIX	LOAD SIZE	CY/M3 ORDERED	ZONE	DRIVER/TRUCK #	COUNTER START	TICKET #
13:37	313	4.00	4.00	Contact Contact	161	0.00	170657
DATE	P.O. #	LOAD#	CY/M3 DEL.	BATCH #	WATER TRIM	SLUMP	PLANT
10/03/2019	3200023428.	3/11/22/2011 0	4.00			4.00	NRMCA PLA

WARNING **IRRITATING TO THE SKIN AND EYES**

Contains Portland Cement. Wear Rubber Boots and Gloves. PROLONGED CONTACT MAY CAUSE BURNS. Avoid Contact With Eyes and Prolonged Contact With Skin. In Case of Contact With Skin or Eyes, Flush Thoroughly With Water. If Irritation Persists, Get Medical Attention. KEEP AWAY FROM CHILDREN

I HAVE READ AND **UNDERSTAND ALL** WARNINGS, PROPERTY DAMAGE RELEASE INFORMATION AND WARRANTY INFORMATION ON THE REVERSE SIDE OF THIS TICKET.

Excessive Water is Detrimental to Concrete Performance H₂O Added By Request/Authorized By

GAL X

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE, DAMAGE RELEASE AND WARRANTY INFORMATION ON THE REVERSE SIDE OF FORM.

	CODE	DESCRIPTION			UNIT PRICE EXTENDED PRIC
	teo BY Sh	40000 HPC ENVIRONENTE ND SHORT LOAD AWW GLASS	UNDER S CY	C9114 31#24 154 N West ATLane Approch	Time 14:08 Amb 60° conc 76° Stump 64
RETURNED TO PLANT	Day 1270	FINISH UNLOADING	\$ 20 B	DELAY EXPLANATION/CYLINDER TEST TAKEN	
TETUTIVED TO LEAVE	LLI I JUD	THIOTICINEOADING	TIVLE ALLOWED		91.
				1. JOB NOT READY 6. TRUCK BROKE DOW	881
		1 7	STEASON	2. SLOW POUR OR PUMP 7. ACCIDENT 3. TRUCK AHEAD ON JOB 8. CITATION	
LEFT PLANT	ARRIVED JOB	START UNLOADING	THEADY	2 SLOW POUR OR PUMP 7 ACCIDENT 3 TRUCK AHEAD ON JOB 8 CITATION 4 CONTRACTOR BROKE DOWN 9 OTHER	
LEFT PLANT	ARRIVED JOB	START UNLOADING	THE ASSESSMENT	2 SLOW POUR OR PUMP 7 ACCIDENT 3 TRUCK AHEAD ON JOB 8 CITATION	
LEFT PLANT	ARRIVED JOB	START UNLOADING	TALESTIC	2 SLOW POUR OR PUMP 7 ACCIDENT 3 TRUCK AHEAD ON JOB 8 CITATION 4 CONTRACTOR BROKE DOWN 9 OTHER	Subtotal:
LEFT PLANT 1.50 TOTAL ROUND TRIP	ARRIVED JOB	START UNLOADING UNLOADING TIME	CEMPS MODE	2. SLOW POUR OR PUMP 7. ACCIDENT 3. TRUCK AHEAD ON JOB 8. CITATION 4. CONTRACTOR BROKE DOWN 9. OTHER 5. ADDED WATER	
1:50		See assist comes	CEMB1: MTE-	2. SLOW POUR OR PUMP 7. ACCIDENT 3. TRUCK AHEAD ON JOB 8, CITATION 4. CONTRACTOR BROKE DOWN 9. OTHER 5. ADDED WATER	Subtotal:

Dane frime		Q. i	er herb	True	zk.	Miscode	Cursome	er N	ame/Id 988	44
10/03/2019	19:95		170697	161		313	GRAHAM	COR	PRACTEMS 570	
daterial	880	Target	Actual	Unit	Vara	Wasc	Moist	- 1	Load	4.00
1 1/2	127	2,893	2,880	Lb	-0.5	-1.73	-0.50m	Î	Returned	0.00
3/4	1200	4,800	4,760	Lb	-6.8	0.00	0.00m	1	Mix Slump	4.00
EMOS CEMOS	1205 480 100	5,012 1,920 400	5,020 1,930 385	lb lb	0.1 0.5 -3.8		4.00m	1	Mix Wat(GL) Trim Wat(GL) Truck Wat(GL)	0.00
ATO1	27.50	81.69	84.00	gal	2.8			- 1	Act Wat (GL)	107.59
IWRA	98.00	144.00	144.00	OS	0.0			- 4	Add Wat (GL)	2.17
BAE90	3.30	15.20	15.00	10.55	-1.3			1	Min Wt/Cm (395
							7	1	Act Wt/Cm ().387(PTY

PHONE 509-933-7050

ELLENSBURG CEMENT PRODUCTS, INC.

CRUSHED GRAVEL WASHED SAND & GRAVEL

READY MIXED CONCRETE

CONT. REG. # ELLEN CP 225 DP

PRICE ALLOWS 8 MINUTES PER YARD TO UNLOAD TRUCK AFTER ARRIVAL. ALL TIME OVER THIS CHARGED FOR AT CURRENT RATES.

CUSTOMER IS RESPONSIBLE FOR PROVIDING ACCEPTABLE WASHDOWN AREA.

SHIP TO:

SOLD TO:

GRAHAM CONTRACTING LTD 550 ise AVE 5 SEATTLE WA 98104 YAKIMA RIVER BRIDGES I 90 MP 102 COME IN ON east END OF BRIDGE

98844

WERIFY DESIGNATED WASHOUT

TIME	MIX	LOAD SIZE	CY/M3 ORDERED	ZONE	DRIVER/TRUCK #	COUNTER START	TICKET #
06:07	313	3.00	35.00		154	0.00	170691
DATE	P.O. #	LOAD #	CY/M3 DEL.	BATCH #	WATER TRIM	SLUMP	PLANT
10/04/2019	-# 3200023428	, in party ALS	3.00			4.00	NRMCA PL'

WARNING IRRITATING TO THE SKIN AND EYES

Contains Portland Cement. Wear Rubber Boots and Gloves. PROLONGED CONTACT MAY CAUSE BURNS. Avoid Contact With Eyes and Prolonged Contact With Skin. In Case of Contact With Skin or Eyes, Flush Thoroughly With Water. If Irritation Persists, Get Medical Attention. KEEP AWAY FROM CHILDREN I HAVE READ AND
UNDERSTAND ALL
WARNINGS, PROPERTY
DAMAGE RELEASE
INFORMATION AND
WARRANTY INFORMATION
ON THE REVERSE SIDE OF
THIS TICKET.

Excessive Water is Detrimental to Concrete Performance H₂O Added By Request/Authorized By

GAL :

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE, DAMAGE RELEASE AND WARRANTY INFORMATION ON THE REVERSE SIDE OF FORM.

UNIT PRICE

LOAD RECEIVED BY

QUANTITY CODE DESCRIPTION

3.00 313 40000 H9C EBURG

2.00 4 ENVIROMENTAL FEE

1.00 SHORT LOAD SHORT LOAD UNDER 5 CY

1270

RETURNED TO PLANT	LEFT JOB	FINISH UNLOADING	TIME ALLOWED	DELAY EXPLANATION/CYLINDER TEST TAK	EN		
			e valenin	1. JOB NOT READY 2. SLOW POUR OR PUMP 3. TRUCK AHEAD ON JOB 8. CITATION	IWN		
LEFT PLANT	ARRIVED JOB	START UNLOADING		4. CONTRACTOR BROKE DOWN 9. OTHER 5. ADDED WATER	v		
6.20	6.30	6:35	المحرود مستوري تروائي والهورية المحرودية		14		
TOTAL ROUND TRIP	TOTAL AT JOB	UNLOADING TIME	CEMO1 - MPR	-TL-2018-11	111		
- A		7:30	CEM02: 12	12-10 Chass F			

Jun 6: 42 // (
Amb 39
Core 61
Slump Q"
Air G.J

EXTENDED PRICE

Subtotal: Tax:

RAND TOTAL

BATCH DATA	11								
Ombe/Time 10/04/2019	06:07		cket 170691	True 154		MixCode 313		mer Name/Id M CONTRACTING LT	98844 ' D /
Material 1 1/2 3/4 > SAND > CEMOS - CEMO2 > WATO1 MWRA MBAE90	38D 727 1200 1205 480 100 27.50 36.00 3.80	Trages 2,170 3,500 0,759 1,460 900 81.27 108.88 11.40	Actual 2,140 3,580 3,920 1,465 310 64.00 108.00 11.00	Unit 1b 1b 1b 1b 1c cs cs	Var9 -1.4 -0.6 4.3 1.7 3.3 4.5 0.0	-1.30 8.00 18.03	Moist -0.50m 0.00m 4.00m	Load Returned Mix Slump Mix Wat (GI Trim Wat (GI Truck Wat (GI Act Wat (GI Add Wat (GI Mix Wt/Cm Act Wt/Cm	GL) 0.00 GL) 0.00 a) 82.45 a) 1.71 0.3954 0.3874
						WEIGHMA	STER SIGNATURE	Χ	

PHONE 509-933-7050

ELLENSBURG CEMENT PRODUCTS, INC.

READY MIXED CONCRETE

PRICE ALLOWS 8 MINUTES PER YARD TO UNLOAD TRUCK AFTER ARRIVAL. ALL TIME OVER THIS CHARGED FOR AT CURRENT RATES.

CUSTOMER IS RESPONSIBLE FOR PROVIDING ACCEPTABLE WASHDOWN AREA.

CRUSHED GRAVEL WASHED SAND & GRAVEL

GRAHAM CONTRACTING LTD 500 Let AVE 5

SERTTLE WA 98104

CONT. REG. # ELLEN CP 225 DP

SHIP TO: YAKIMA RIVER BRIDGES COME IN ON WEST END OF BRIDGE

99544

SOLD TO:

MERIFY DESIGNATED WASHOUT

TIME	MIX	LOAD SIZE	CY/M3 ORDERED	ZONE	DRIVER/TRUCK #	COUNTER START	TICKET #
97:30	913	5_00	28.00		151	0100	170701
DATE	P.O. #	LOAD #	CY/M3 DEL.	BATCH #	WATER TRIM	SLUMP	PLANT
10/04/2019	320002942 E		9.00			4_00	NAMCA PLE

WARNING **IRRITATING TO THE SKIN AND EYES**

Contains Portland Cement, Wear Rubber Boots and Gloves. PROLONGED CONTACT MAY CAUSE BURNS. Avoid Contact With Eyes and Prolonged Contact With Skin. In Case of Contact With Skin or Eyes, Flush Thoroughly With Water. If Irritation Persists, Get Medical Attention. KEEP AWAY FROM CHILDREN

I HAVE READ AND **UNDERSTAND ALL** WARNINGS, PROPERTY DAMAGE RELEASE INFORMATION AND WARRANTY INFORMATION ON THE REVERSE SIDE OF THIS TICKET.

X

Excessive Water is Detrimental to Concrete Performance H₂O Added By Request/Authorized By

GAL X

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE, DAMAGE RELEASE AND WARRANTY INFORMATION ON THE REVERSE SIDE OF FORM.

QUANTITY	CODE	DESCRIPTION	e professional designation of the second	the state of the s		UNIT PRICE	EXTENDED PRICE
6.00 6.00	4 313	4000D HPC ENVIROMENTS	EBURG AL FEE	C9214 BI#24 15410 Sep #5		Time \$:05	2/2
2 4	s Dary	1270ab	41	A 4 2/B	alberg and the	Amb 39° Conz 66° Slump 61%	
RETURNED TO PLANT	LEFT JOB	FINISH UNLOADING	TIME ALLOWED	DELAY EXPLANATION/CYI		Air 5.7	
	7-1-		YEZAME	1 JOB NOT READY 2 SLOW POUR OR PUMP 3 TRUCK AHEAD ON JOB	6. TRUCK BROKE DOWN 7. ACCIDENT 8. CITATION	Tester: Tony ACI#	madisan
LEFT PLANT	ARRIVED JOB	START UNLOADING		4_ CONTRACTOR BROKE DOWN 5_ ADDED WATER	9 OTHER	ACIT	The Control
745		8109			ULANGE STILL	Subtetal	
TOTAL ROUND TRIP	TOTAL AT JOB	UNLOADING TIME	CEMOI: MTR	-T1-2018-11	inise in elem	Tar :	
	- v - samuest	813	CEM02: 12-		sort duft s	GRAND TOTAL	

BATCH DATA					
Duts/Time 10/04/2019 07:30	Ticket 170701	Truck 151	MixCode 313		Name/Id \$0044 ONTRACTING LTD
 Material 33D 1 1/2 727 3/4 1260 3AND 1205 CEM03 480 CEM02 100 WAT01 27.50 MWRA 36.00	Target Actual 4,340 4,300 7,200 7,140 7,519 7,520 2,380 2,355 600 610 122,54 125.00 216.00 812.00	1b -0.0 1b 0.0 1b -0.9 1b 1.7 gal 2.0	-2.50 0.00 36.06	Moist -0.50m 0.80m 4.00m	Load 6.00 Returned 0.00 Min Slump 4.00 Min Wat (GL) 125.00 Trim Wat (GL) 0.00 Truck Wat (GL) 0.00 Act Wat (GL) 160.32 Add Wat (GL) 3.97
MBAE90 3.90	22.90 22.00			ter signature X _	Mix Wt/Cm

PHONE 509-933-7050

ELLENSBURG CEMENT PRODUCTS, INC.

CRUSHED GRAVEL WASHED SAND & GRAVEL

READY MIXED CONCRETE

CONT. REG. # ELLEN CP 225 DP

PRICE ALLOWS 8 MINUTES PER YARD TO UNLOAD TRUCK AFTER ARRIVAL. ALL TIME OVER THIS CHARGED FOR AT CURRENT RATES.

CUSTOMER IS RESPONSIBLE FOR PROVIDING ACCEPTABLE WASHDOWN AREA.

SHIP TO:

SOLD TO:

GRAHAM CONTRACTING LTD 568 lat AVE S SEATTLE WA 98104

98844

YAKIMA RIVER BRIDGES MP 1.02 COME IN ON WEST END OF BRIDGE

VERIFY DESIGNATED WASHOUT

TIME	MIX	LOAD SIZE	CY/M3 ORDERED	ZONE	DRIVER/TRUCK #	COUNTER START	TICKET #
08:47	313	5,00	25:00		151	0.00	170707
DATE	P.O. #	LOAD #	CY/M3 DEL.	BATCH #	WATER TRIM	SLUMP	PLANT
10/04/2019	3200023422		15.00			4.00	NRMCA PLO
10/04/2019	320002342		15.00				

WARNING IRRITATING TO THE SKIN AND EYES

Contains Portland Cement. Wear Rubber Boots and Gloves, PROLONGED CONTACT MAY CAUSE BURNS. Avoid Contact With Eyes and Prolonged Contact With Skin. In Case of Contact With Skin or Eyes, Flush Thoroughly With Water. If Irritation Persists, Get Medical Attention. KEEP AWAY FROM CHILDREN

I HAVE READ AND **UNDERSTAND ALL** WARNINGS, PROPERTY DAMAGE RELEASE INFORMATION AND WARRANTY INFORMATION ON THE REVERSE SIDE OF THIS TICKET.

Excessive Water is Detrimental to Concrete Performance H₂O Added By Request/Authorized By

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE, DAMAGE RELEASE AND WARRANTY INFORMATION ON THE REVERSE SIDE OF FORM.

UNIT PRICE

DESCRIPTION CODE QUANTITY 313 4000D HPC REURG 6.00 6.00 ENVIROMENTAL FEE

EXTENDED PRICE

ANATION/CYLINDER TEST TAKEN	D DELAY	TIME ALLOWED	FINISH UNLOADING	LEFT JOB	RETURNED TO PLANT
OR PUMP 7. ACCIDENT	1 JOB N 2 SLOW 3 TRUC	revis.			
	5 ADDE		START UNLOADING	ARRIVED JOB	LEFT PLANT
	THE STATE OF		4)	11 1 N	000
الأعلاء السيسيمييين لا البر			9108	West Visit	750
9-11	MR-IL-2	CEMO1: M	UNLOADING TIME	TOTAL AT JOB	TOTAL ROUND TRIP
	2-18 CL	THE REAL PROPERTY AND ADDRESS OF THE PARTY AND	14:38		

Χ.

BATCH DATA					y I -	for a		
Date/Time 10/04/2019	08:47		cket 170707	Teuc 151		MixCode 313		er Name/Id 98844 CONTRACTING LTD
Material 1 1/2 3/4 SAND CEMOS CHMOS WATO! MWRA MBAEGO	25D 727 1200 1205 480 100 27.50 26.00 2.80	Target 4,340 7,200 7,519 2,980 600 192.54 216.00 22.80	Actual 4,360 7,140 7,480 2,895 605 125.00 216.00 22.90	Unit 1b 1b 1b 1b 1c ggl os	Vac 4 0.5 -0.6 -0.5 0.6 0.0 -0.6	WatC -2.50 0.00 36.06	Moist -0.50m 6.00m 4.00m	Losd
						WEIGHMA	STER SIGNATURE	Χ

PHONE 509-933-7050

ELLENSBURG CEMENT PRODUCTS, INC.

CRUSHED GRAVEL WASHED SAND & GRAVEL

READY MIXED CONCRETE

CONT. REG. # ELLEN CP 225 DP

PRICE ALLOWS 8 MINUTES PER YARD TO UNLOAD TRUCK AFTER ARRIVAL. ALL TIME OVER THIS CHARGED FOR AT CURRENT RATES.

CUSTOMER IS RESPONSIBLE FOR PROVIDING ACCEPTABLE WASHDOWN AREA.

SHIP TO:

SOLD TO:

GRAHAM CONTRACTING LTD 568 1st AVE 3. 3EATFLE WA 95209

90344

YAKIMA RIVER BRIDGES TI DO MP 102 COME IN ON WEST END OF BRIDGE

WERTET DESIGNATED NASHOUT

TIME	MIX	LOAD SIZE	CY/M3 ORDERED	ZONE	DRIVER/TRUCK #	COUNTER START	TICKET #
09:40	313	8.00	25.00	\$ manage	152	0.00	170710
DATE	P.O. #	LOAD #	CY/M3 DEL	BATCH#	WATER TRIM	SLUMP	PLANT
10/04/2019	3200023428		29.00			24.00	NAMEA RES
	WARRING	Company of the second			Evennius Water	a Detrimental to Con	

WARNING IRRITATING TO THE SKIN AND EYES

Contains Portland Cement. Wear Rubber Boots and Gloves. PROLONGED CONTACT MAY CAUSE BURNS. Avoid Contact With Eyes and Prolonged Contact With Skin. In Case of Contact With Skin or Eyes, Flush Thoroughly With Water. If Irritation Persists, Get Medical Attention. KEEP AWAY FROM CHILDREN I HAVE READ AND UNDERSTAND ALL WARNINGS, PROPERTY DAMAGE RELEASE INFORMATION AND WARRANTY INFORMATION ON THE REVERSE SIDE OF THIS TICKET.

Excessive Water is Detrimental to Concrete Performance H₂O Added By Request/Authorized By

_GAL X

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE, DAMAGE RELEASE AND WARRANTY INFORMATION ON THE REVERSE SIDE OF FORM.

LOAD RECEIVED BY

5/

RETURNED TO PLANT	LEFT JOB	FINISH UNLOADING	TIME ALLOWED	DELAY EXPLANATION/CY	LINDER TEST TAKEN
			- Angragal	1, JOB NOT READY 2. SLOW POUR OR PUMP 3. TRUCK AHEAD ON JOB	6. TRUCK BROKE DOWN 7. ACCIDENT 8. CITATION
LEFT PLANT	ARRIVED JOB	START UNLOADING	10+	34 DOONTRACTOR BROKE DOWN 5. ADDED WATER	9 OTHER
951	1666	1002			
TOTAL ROUND TRIP	TOTAL AT JOB	UNLOADING TIME	CENTAL MED.	TI-2018-11	to separate them
		10:45	-CEM02: 12-1	-	

il suis I

GRAND TOTAL

Subject of

BATCH DATA		1	
Date/Time 10/04/2019 09:40	Tighet 170710	Truck MixCode	Curtomer Name/Id 98546 GRAHAM CONTRACTING LTD
Material 33D 1 1/2 727 3/4 1200 5AND 1205 CEM03 480 CEM02 100 WAT01 27.50 MWRA 36.00 MBAE90 3.80	Target Actual 5,786 5,920 9,540 10,025 10,000 2,640 2,560 785 165 20 165 20 20 20 20 20 20 20 20 20 20 20 20 20	15 -0.6 -0.00 15 -0.3 48.38 15 0.5 15 -1.8 gsl 1.5 0.0 0.0 0.0 0.0	Moist Load 8.00 -0.50m Returned 6.00 0.00m Mak, Jump 4.00 4.00m Mik Sit (GL) 155.00 True Wat (GL) 0.00 True Wat (GL) 0.00 Act Wat (GL) 7.20 Mix Wt/Cm 0.3958 Act Wt/Cm 0.3958 Act Wt/Cm 0.3924 ADMIX NOT EMPTY
	Myster 1	WEIGHMAS	STER SIGNATURE X

PHONE 509-933-7050

ELLENSBURG CEMENT PRODUCTS, INC.

CRUSHED GRAVEL WASHED SAND & GRAVEL

READY MIXED CONCRETE

CONT. REG. # ELLEN CP 225 DP

PRICE ALLOWS 8 MINUTES PER YARD TO UNLOAD TRUCK AFTER ARRIVAL. ALL TIME OVER THIS CHARGED FOR AT CURRENT RATES.

CUSTOMER IS RESPONSIBLE FOR PROVIDING ACCEPTABLE WASHDOWN AREA.

SHIP TO:

SOLD TO:

GRAHAM CONTRACTING LTD 568 let AVE S SEATTLE WA 90104

YAKINA RIVER BRIDGES 1 90 MP 102 COME IN ON WEST END OF BRIDGE

99844

VERIFY DESIGNATED WASHOUT

TIME	MIX	LOAD SIZE	CY/M3 ORDERED	ZONE	DRIVER/TRUCK #	COUNTER START	TICKET #
10:22	313	8,00	35.00		153	0_00	170712
DATE	P.O. #	LOAD #	CY/M3 DEL.	BATCH #	WATER TRIM	SLUMP	PLANT
10/04/2019	2200023425		31.00			4.00	NRMCA PLA

WARNING **IRRITATING TO THE SKIN AND EYES**

Contains Portland Cement. Wear Rubber Boots and Gloves. PROLONGED CONTACT MAY CAUSE BURNS. Avoid Contact With Eyes and Prolonged Contact With Skin. In Case of Contact With Skin or Eyes, Flush Thoroughly With Water. If Irritation Persists, Get Medical Attention. KEEP AWAY FROM CHILDREN

I HAVE READ AND **UNDERSTAND ALL** WARNINGS, PROPERTY DAMAGE RELEASE INFORMATION AND WARRANTY INFORMATION ON THE REVERSE SIDE OF THIS TICKET.

Excessive Water is Detrimental to Concrete Performance H₂O Added By Request/Authorized By

GAL X

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE, DAMAGE RELEASE AND WARRANTY INFORMATION ON THE REVERSE SIDE OF FORM.

LOAD RECEIVED BY:

EXTENDED PRICE QUANTITY CODE DESCRIPTION UNIT PRICE 8.00 4000D HPC EBURG 8.00 ENVIROMENTAL FEE

LEFT JOB FINISH UNLOADING TIME ALLOWED DELAY EXPLANATION/CYLINDER TEST TAKEN RETURNED TO PLANT 6. TRUCK BROKE DOWN SLOW POUR OR PUMP TRUCK AHEAD ON JOB 8. CITATION 4. CONTRACTOR BROKE DOWN 5. ADDED WATER LEFT PLANT START UNLOADING ARRIVED JOB 1025 10:55 TOTAL ROUND TRIP TOTAL AT JOB **UNLOADING TIME** CEMANO. 10-12 CINES E

Subtobal:

GRAND TOTAL

Past

BATCH DATA		1					-91	
Date/Time 10/04/2019	10:22		oket 170712	True 153	rån	MixCode 212		er Name/Id 93344 CONTRACTING LTD
Material 1 1/2 5/4 SAND CEMOS CEMOS WATOL MURA MUSAESO	88D 727 1200 1205 480 100 27.50 25.00 3.80	Targer 5,786 9,500 10,025 3,540 900 155.26 288.00	Actual 5,800 9,520 2,840 790 158.00 285.00	lb lb lb lb lb gal	Vara 0.2 -0.3 -0.9 0.0 -1.2 0.0 -1.3	-3.47 0.00 48.08	Moist -0.50m 0.00m 4.00m 17841	Load
						WEIGHMA	STER SIGNATURE	X

PHONE 509-933-7050

ELLENSBURG

CEMENT PRODUCTS, INC.

PRICE ALLOWS 8 MINUTES PER YARD TO UNLOAD TRUCK AFTER ARRIVAL. ALL TIME OVER THIS CHARGED FOR AT CURRENT RATES.

CRUSHED GRAVEL WASHED SAND & GRAVEL

READY MIXED CONCRETE

CONT. REG. # ELLEN CP 225 DP

CUSTOMER IS RESPONSIBLE FOR PROVIDING ACCEPTABLE WASHDOWN AREA.

SHIP TO:

SOLD TO:

GRAHAM CONTRACTING LTD 568 Let AVE 3 SEATTLE MA 99104

YAKIMA RIVER BRIDGES COME IN ON WEST END OF BRIDGE

요원원관리

MERIFY DESIGNATED WASHOUT

TIME '	MIX	LOAD SIZE	CY/M3 ORDERED	ZONE	DRIVER/TRUCK #	COUNTER START	TICKET #
11:14	218	5.00	36.700		151	0.00	170714
DATE	P.O. #	LOAD #	CY/M3 DEL.	BATCH #	WATER TRIM	SLUMP	PLANT
10/04/2019	32000224265		35.00	Telegraphics	CALL DESCRIPTION	4.00	NRMCA PLS

WARNING **IRRITATING TO THE SKIN AND EYES**

Contains Portland Cement. Wear Rubber Boots and Gloves. PROLONGED CONTACT MAY CAUSE BURNS. Avoid Contact With Eyes and Prolonged Contact With Skin. In Case of Contact With Skin or Eyes, Flush Thoroughly With Water. If Irritation Persists, Get Medical Attention. KEEP AWAY FROM CHILDREN

I HAVE READ AND **UNDERSTAND ALL** WARNINGS, PROPERTY DAMAGE RELEASE INFORMATION AND WARRANTY INFORMATION ON THE REVERSE SIDE OF THIS TICKET.

Excessive Water is Detrimental to Concrete Performance H₂O Added By Request/Authorized By

NOTICE: MY SIGNATURE BELOW INDICATES THAT I HAVE READ THE HEALTH WARNING NOTICE, DAMAGE RELEASE AND WARRANTY INFORMATION ON THE REVERSE SIDE OF FORM.

UNIT PRICE

LOAD RECEIVED BY:

QUANTITY CODE DESCRIPTION 5.00 4000D HEC . EBURG 5.00 ENVIRONENTAL FEE

EXTENDED PRICE

RETURNED TO PLANT	LEFT JOB	FINISH UNLOADING	TIME ALLOWED	, DELAY EXPLANATION/CYLINDER TEST TAKEN	The property in the party of
	W.		replan.	1 JOB NOT READY 6. TRUCK BROKE DOWN 2. SLOW POUR OR PUMP 7. ACCIDENT 3. TRUCK AREAD ON JOB 8. *CITATION	
LEFT PLANT	_ ARRIVED JOB	START UNLOADING	15 - 15 - 1	4. CONTRACTOR BROKE DOWN 9. OTHER 5. ADDED WATER	100
1130	11:33	11:40		<u>j (1831 delenderen er en skræskeld</u> An 1870 geografisk	Subtoba
TOTAL ROUND TRIP	TOTAL AT JOB	UNLOADING TIME	CEMO3 MTR	-TL-2018-11	Tauc :
		12:05	12. EXP X 17 16.7 X 3.16.	19 CLASS F';	GRAND TOTAL

BATCH DATA		-4	7		- 4				
Date/Time 10/08/2019 11:14		Ticket - 170714		Truck MixCode			ner Mame/Id 99944 A CONTRACTING LTD		
Material 1 1/2 2/6 SAND CEMOS CEMOS CEMOS MATOI MURA MEAESO	78D 727 1200 1205 0 100 490 27.50 3.90	Target 3,616 6,000 6,265 0 500 2,400 102,12 180.00 13.00	Actual 2,520 5,980 5,280 0 510 2,380 105_00 150.00	Unit 1b 1b 1b 1b 1b 1h cal	Vara 9.1 -0.7 -0.1 2.0 -0.8 0.0	WatC -2.17 0.00 30.05	Moist -0.50m 0.00m 4.00m	Load	
						WEIGHMA	STER SIGNATURE	X	